



Vista edificio da via Roma frontale	Vista edificio da via Roma lato sinistro
	
Prospetto sud-ovest (affaccio appartamento)	Prospetto nord-est
	
Part. carbonatazione prosp. Nord-est	Vialeto di ingresso civico 19
	



<p>Ingresso - corpo scala condominio</p> 	<p>Androne ingresso</p> 
<p>Pianerottolo piano terra</p> 	<p>Particolare corpo scale</p> 
<p>Porta di entrata appartamento</p> 	<p>Ingresso appartamento</p> 




<p>Vista cucina abitabile</p> 	<p>Cucina vista dall'interno</p> 
<p>Soggiorno visto dal lato finestra</p> 	<p>Soggiorno visto dall'ingresso</p> 
<p>Bagno visto dal disimpegno</p> 	<p>Bagno visto dalla finestra</p> 



Disimpegno cabina armadio	Interno cabina armadio
 A photograph showing a hallway or entrance area with light-colored tiled flooring and white walls. A wooden door frame is visible on the left, and a white pillar or wall section is on the right.	 A photograph of an empty room with light-colored tiled flooring and white walls. A wooden door frame is visible on the right side.
Presca d'aria/luce cabina armadio	Camera da letto vista dalla porta
 A photograph showing a view into a room with a white ceiling, a light fixture, and a wooden door frame. A mirror is mounted on the wall.	 A photograph of a bedroom with light-colored tiled flooring, white walls, and a window with a radiator below it. A wooden door frame is visible on the left.
Camera da letto vista dalla finestra	Particolare radiatori - valvole termostatiche
 A photograph of a bedroom with light-colored tiled flooring, white walls, and a wooden door frame. A window is visible on the left.	 A close-up photograph of a white radiator with a thermostatic valve.



<p>Particolare aria condizionata - split</p> 	<p>Part. aria condizionata - motocondensante</p> 
<p>Particolare serramenti</p> 	<p>Balcone</p> 
<p>Corridoio cantine</p> 	<p>Cantina di proprietà</p> 

